



Product Release Information: LEB Firmware 03.11.02

Product	LEB
Version Number	03.11.02
Firmware Release Date	February 2023
Customer Support	For more information or support, visit the ENGAGE website.

Attention:

This document contains the **Release Notes** for LEB device firmware version **03.11.02**. This version includes feature updates and improvements made after the LEB firmware 03.10.01 released in June of 2022.

Installation and Update Notes:

Device firmware updates are available through the ENGAGE™ cloud database.

From the ENGAGE web portal, each lock may be independently selected by the site administrator to have the latest firmware downloaded during the next scheduled Wi-Fi connection. Alternatively, the site administrator may connect locally to individual locks with the ENGAGE mobile application to update an LEB with the latest firmware.

Firmware versions that will be installed with this update:

- **Main Application** **03.11.02**
- **Reader Application** **02.13.00**
- *BLE Application* 02.13.06.327,01.10.03,01-1.7.0
- Wi-Fi Application: 02.10.0.0

NOTE: The **BOLD** item(s) are updated from the previous release

Other system components versions to be used with this release: (or newer)

- Gateway 01.61.06
- MT20W 40.05.00
- Android Application **4.7.33**
- iOS application **3.10.0**
- ENGAGE **8.2.0**



Who should update?

Allegion suggests that customers utilize the latest firmware release to take advantage of the latest functionality, bug fixes, and security enhancements. We strive to provide the best products and service for our customers.

Specifically, any customer interested in any of the following New Features and Recent Changes should update their devices.

New Features:

- Support added to convert card reader output to simulate MagStripe Track 2
 - Card Data can be up to 8-byte hexadecimal that represents up to 19-digit decimal primary account number (PAN)
 - Card Data up to 64 bits may be converted from any source
 - Config Card CE-404-178 is used to enable the feature
 - Config Card CE-404-179 is used to disable this feature
- Note:** Card Data is only converted when it is less than or equal to 8 bytes
Note: This only converts card reader output. Mag stripe cards will not be read

Recent Changes:

- Fixed an issue where HID LEBs failed to give a long red flash if presented with an invalid config card

Revision	COMMENTS	DATE
SES20230112A	Release Notes for LEB as part of ENGAGE 8.2.0	01-12-23