

Product Release Information: Reader Controller Firmware 01.08.06

Product	RC11, RC15, RCK15
Version Number	01.08.06
Firmware Release Date	January 2023
Customer Support	For more information or support, visit the ENGAGE website.

Attention:

This document contains the **Release Notes** for Reader Controller firmware version **01.08.06**. The version includes feature updates and improvements made after the RC firmware 01.08.02 released in August of 2022.

Installation and Update Notes:

Installation:

Device firmware updates are made available through the Pure Access Software.

The Reader Controller firmware is updated using by selecting Device Update in the Pure Access software.

Firmware versions that will be installed with this update:

- **Main Application** **01.08.06**
- **Reader Application** **2.13.00**
- **BLE Application** *02.13.06.327, 01.10.03, 01-1.7.0*

NOTE: The **BOLD** item(s) are updated from the previous release

Other system components versions to be used with this release: (or newer)

- **Android Application** **4.7.33**
- **iOS application** **3.10.0**
- **ENGAGE** **8.2.0**



Who should update?

Allegion recommends keeping all devices at your site up to date with the latest firmware and software. We strive to provide the best products and service for our customers and security upgrades are highly recommended.

Our latest firmware and software releases will allow the customer to get the most from their devices.

Specifically, all customers who would be interested in the following Recent Changes should update their devices.

Recent Changes:

- Fixed an issue where if a Firmware Package download failed, the RC could get stuck in a retry loop
- Fixed an issue where if invalid JSON tags are sent, Audit ID “0900 0001” was not generated
- Fixed an issue where an audit for “Auto Relock Event First Person In – Secure” was not generated
- Aligned Schlage RC handling of certificates with multiple sub domains to Schlage NDEB
- RC will no longer accept invalid ASCII characters for the device name
- Fixed an issue where the device would be locked after power cycle with the Aux switch ON

Revision	COMMENTS	DATE
SES20230110A	ENGAGE 8.2.0 Reader Controller Update	01/10/2023