



**Product Release Information: XE360 Firmware 01.00.00**

<b>Product</b>	XE360
<b>Version Number</b>	01.00.00
<b>Firmware Release Date</b>	February 2025
<b>Customer Support</b>	For more information or support, visit the <a href="#">ENGAGE</a> website.

**Attention:**

This document contains the **Release Notes** for XE360 device firmware version **01.00.00**. This version includes feature updates and improvements made after initial release of XE360.

**Installation and Update Notes:**

Device firmware updates are available through the ENGAGE™.

Each lock may be updated to the latest firmware by connecting locally to individual locks with the ENGAGE mobile application.

Firmware versions that will be installed with this update:

- **Main App**                      **02.01.000003**
- **Reader App**                    **02.01.000003**
- BLE Application                01.00.536869-BL:02.01.000000-SE:01.02.13
- Main BL                         01.00.000001
- Reader BL                      02.00.000001

NOTE: The **BOLD** item(s) are updated from the previous release

Other system components versions to be used with this release: (or newer)

- MT20W                         41.00.00
- Android Application        4.7.857
- iOS application              3.15.0
- ENGAGE                        8.5.2



**Who should update?**

Allegion suggests that customers utilize the latest firmware release to take advantage of the latest functionality, bug fixes, and security enhancements. We strive to provide the best products and service for our customers.

Specifically, any customer interested in any of the following New Feature and Recent Changes should update their devices.

**New Features:**

- TRA Configuration feature for Apple NFC
  - Additional security for Apple NFC credentials by using Apple login credentials when the phone screen is locked

**Recent Changes:**

- Fixed an issue with Case Sensitivity in the Serial Number in the Door File
- Fixed an issue where Audits were not deleted after Uploading with the Mobile App
- Fixed an incorrect use of the 0x0000 error code while reading audits
- Fix an issue where the BLE Time Characteristic was not responding with the locks Real Time Clock value
- Corrected Database Download Time and Next Database Version time stamps in the GetConfig read response
- Improvements made around battery life for Apple Mobile NFC
- Implemented Database full erase using DB Tag DeleteAll

<b>Revision</b>	<b>COMMENTS</b>	<b>DATE</b>
SES20250201A	Release Notes for XE360 01.00.00	02-01-25