

# **Product Release Information: LE Firmware 01.15.02**

Product	LE
Version Number	01.15.02
Firmware Release Date	March 2024
<b>Customer Support</b>	For more information or support, visit the <b>ENGAGE</b> website.

## **Attention:**

This document contains the **Release Notes** for LE device firmware version **01.15.02.** This version includes feature updates and improvements made after the LE product firmware 01.14.01 released in August of 2023.

# **Installation and Update Notes:**

Device firmware updates are available through the ENGAGE™ cloud database.

From the ENGAGE web portal, each lock may be independently selected by the site administrator to have the latest firmware downloaded during the next scheduled Wi-Fi connection. The site administrator may connect locally to individual locks with the ENGAGE mobile application to update an LE with the latest firmware.

Firmware versions that will be installed with this update:

Main Application 01.15.02Reader Application 02.19.00

• BLE Application 02.13.06.327,01.10.03,01-1.7.0

Wi-Fi Application: 02.15.0.1

NOTE: The **BOLD** item(s) are updated from the previous release

Other system components versions to be used with this release: (or newer)

Gateway 01.64.04
MT20W 40.07.00
Android Application 4.7.782
iOS application 3.14.0
ENGAGE 8.4.0

#### **LE RELEASE NOTES: LE Firmware 01.15.02**

SES-20240310A



#### Who should update?

Allegion suggests that customers utilize the latest firmware release to take advantage of the latest functionality, bug fixes, and security enhancements. We strive to provide the best products and service for our customers.

Specifically, any customer interested in any of the following Recent Changes should update their devices.

## **Recent Changes:**

- Fixed an issue where the Audit "Unread Audits Overwritten" would be reported more than once when the Maximum number of Audits had been reached
- Fixed an issue where the lock would continue to BLE advertise if Factory Default Reset during commissioning
- Fixed an issue where the lock would not accept a new configuration card after being presented with an iClass Elite card
- Improvements made for Battery Life
- General Security Updates

Revision	COMMENTS	DATE
SES20240310A	Release Notes for LE as part of ENGAGE 8.4.0	03-10-24