

Product Release Information: Reader Controller Firmware 01.09.05

Product	RC11, RC15, RCK15
Version Number	01.09.05
Firmware Release Date	November 2023
Customer Support	For more information or support, visit the ENGAGE website.

Attention:

This document contains the **Release Notes** for Reader Controller firmware version **01.09.05.** The version includes feature updates and improvements made after the RC firmware 01.08.07 released in April of 2023.

Installation and Update Notes:

Installation:

Device firmware updates are made available through the Pure Access Software.

The Reader Controller firmware is updated using by selecting Device Update in the Pure Access software.

Firmware versions that will be installed with this update:

Main Application 01.09.05Reader Application 2.17.00

o BLE Application 02.13.06.327, 01.10.03, 01-1.7.0

NOTE: The **BOLD** item(s) are updated from the previous release

Other system components versions to be used with this release: (or newer)

Android Application
iOS application
ENGAGE
4.7.713
3.12.0
8.3.1



Who should update?

Allegion recommends keeping all devices at your site up to date with the latest firmware and software. We strive to provide the best products and service for our customers and security upgrades are highly recommended.

Our latest firmware and software releases will allow the customer to get the most from their devices.

Specifically, all customers who would be interested in the following New Features and Recent Changes should update their devices.

New Features:

- Access Control Software can now poll Door Status information:
 - Lock State: Locked/Unlocked
 - Door Position: Open/Closed/Unknown(if DPS not configured)
 - o Device State: Schedule vs. Override vs. Standard Credential
- Door Status is now reported when the device connects to Access Control Software
- Enrollment Reader Functionality
 - Schlage RC may now be used as an enrollment reader

NOTE: This feature requires Device firmware version A.07 or later

- "nextDBverTS" Tag implemented
 - This tag is used by Access Control Software to determine if the device has the latest database update

Recent Changes:

- Improved reconnect functionality and scenarios where a disconnect might have occurred
- Fixed an issue where an Extended Schedule could be set with a longer than intended time (Max Time: 23:59 HH:MM)
- Fixed an issue where the "Incremential Database User Update Count" audit was being generated more often than intended
- Default Door Prop delay should now be correctly configured to 30 seconds after comissioning

RC RELEASE NOTES: Reader Controller Firmware 01.09.05

SES-20231101A



- Amber and Blue LEDs may now be controlled by the Access Control Software
- Beeper will no longer beep when sent an incorrect value
- Improved Compile performance

Revision	COMMENTS	DATE
SES20231101A	ENGAGE 8.3.1 Reader Controller Update	11/01/2023